

# Inspection Photos

January 23, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 335423

Location Name: SHIDELER-66S92W/29NESW

Inspection Document #: 702801181

Garfield County, CO

NESW Section 29 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SHIDELER-66S92W/29NESW  
Location ID: 335423



1/23/23  
107.693968  
42° NE



**Photo 1.** Photos show production areas.

Inspection Photos  
Location Name: SHIDELER-66S92W/29NESW  
Location ID: 335423



**Photo 2.** Photo shows production areas. Note vegetation growing around wellheads.



## Inspection Photos

Location Name: SHIDELER-66S92W/29NESW

Location ID: 335423



**Photo 3.** Photo shows an unmarked anchor at the northeast of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801181

## Inspection Photos

Location Name: SHIDELER-66S92W/29NESW

Location ID: 335423



**Photo 4.** Photo shows staining beneath a produced water tank drain line.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801181

Inspection Photos  
Location Name: SHIDELER-66S92W/29NESW  
Location ID: 335423



**Photo 5.** Photo shows an example of interim areas. Introduced perennial grasses appear well established.



Inspection Photos  
Location Name: SHIDELER-66S92W/29NESW  
Location ID: 335423



**Photo 6.** Photo shows the pad surface.

