

# Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335781

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



January 25, 2023



January 25, 2023

**Photo 1:** Upper-Location overview. Permanent signage at battery not observed



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



**Photo 2:** Overview of the lower-areas of the Location (east end of the Location).

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



**Photo 3:** Fence in disrepair at the separator equipment.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



**Photo 4:** Photo example showing Operator information label applied to the wells is peeling. Maintenance advised to ensure signage remains legible.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



January 25, 2023



January 25, 2023

**Photo 5:** Photos 5-7 taken from the upper western, and lower eastern areas of the working pad area, and Location entrance. Photos show production areas lack stabilization; BMPs to stabilize the working pad, and to minimize degradation, tracking and off-site sediment transport are missing or insufficient.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



**Photo 6:** See comments under photo 5

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335781



**Photo 7:** See comments under photo 5