

Inspection Photos

01/25/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335581

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 1: Location Overview



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 2: Operator information label attached to sign is peeling off.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



January 25, 2023



January 25, 2023

Photo 3: Tears/rip apparent at base of the liner. Liner does not appear to be impervious.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 4: Wells on Location.

