

Inspection Photos

Pit# 257263

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/27/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

#257263 | Date: 1/27/2023

Inspection Photos




Photo 1. The associated pit has incorrect coordinates showing the pit at red arrow and the well site at yellow arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

#257263 | Date: 1/27/2023