

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

12/08/2021

Document Number:

402892922

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: <u>47120</u>	Contact Person: <u>Jacob Rupert</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(970) 5151943</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>jacob_rupert@oxy.com</u>

Identification Information

API Number: <u>05 - 123-34956</u>	OGCC Facility ID: <u>427351</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>CAMP</u>	Facility Number: <u>37N-26HZ</u>	Facility Type: <u>WELL</u>
Location QtrQtr: <u>NENE</u>	Section: <u>26</u>	Township: <u>3N</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
	County: <u>WELD</u>	Field Name: <u>WATTENBERG</u>
Federal, Indian or State Lease Number: _____		

Information Submitted By:

Company Name: <u>Absaroka Energy and Environmental Solutions</u>	Agent Name: <u>Max Moran</u>	Title: <u>Env. Professional</u>
Phone Number: <u>7203525326</u>	Email: <u>max.moran@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected _____

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>427351</u>	Facility Name: <u>CAMP 37N-26HZ</u>	Facility Type: <u>Oil and Gas Well</u>
Location: QtrQtr: <u>NENE</u>	Sec: <u>26</u>	Twp: <u>3N</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County Name: <u>WELD</u>	Latitude: <u>40.201654</u>	Longitude: <u>-104.737315</u>

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>93538</u>	Document Name: <u>Size of file in bytes: 36864</u>	File Name: <u>2021_09_14_BW_05_123_34956_BHD_Isotech_NG 4_COGCC.xls</u>
SampleType: _____	Matrix: _____	
Facility ID: <u>427351</u>	Sample ID: <u>630371</u>	Sample Name: <u>BW_05_123_34956_BHD</u>
Collection Point: <u>BDH</u>	Matrix: <u>GAS</u>	Pre Post: <u>Bradenhead Water Sample</u>
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	NOAV Number: _____
	Laboratory: <u>ISOTECH</u>	Lab Sample ID: <u>803606</u>

Batch ID: 93540 Document Name: Size of file in bytes: 34816 File Name: 2021_09_14_BW_05_123_34956_BHD_TRIP_BLA
NK_SGS_COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 427351 Sample ID: 630374 Sample Name: BW_05_123_34956_BHD_TRIP_BLANK Sample Date: 09/14/2021

Collection Point: TB Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA37493-1

Batch ID: 93541 Document Name: Size of file in bytes: 34816 File Name: 2021_09_14_SP_05_123_34956_C_Isotech_NG4
COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 427351 Sample ID: 630375 Sample Name: SP_05_123_34956_C Sample Date: 09/14/2021

Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 804838

Batch ID: 93539 Document Name: Size of file in bytes: 65024 File Name: 2021_09_14_BW_05_123_34956_BHD_SGS_COG
CC.xls

SampleType: _____ Matrix: _____

Facility ID: 427351 Sample ID: 630373 Sample Name: BW_05_123_34956_BHD Sample Date: 09/14/2021

Collection Point: BDH Matrix: WATER Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA37492-1

Batch ID: 93538 Document Name: Size of file in bytes: 36864 File Name: 2021_09_14_BW_05_123_34956_BHD_Isotech_NG
4_COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 427351 Sample ID: 630372 Sample Name: BW_05_123_34956_BHD Sample Date: 09/14/2021

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 803606

Sample Facility Attachment:
No Facility Attachment

Sample COGCC Well Related:
No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	01/31/2023
Total: 1 comment(s)		