

# Interim Reclamation and Stormwater Inspection

Date: 01/24/2023

Operator: FUNDARE RESOURCES OPERATING  
COMPANY LLC - 431440

Location ID: 431440

Inspection Document #: 696105701

Weld County, CO

SWSW Section 33 T10N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Razor 33M Pad  
Location ID: 431440



**Photo 1.** Facing northeast near pump jack. Photo illustrates unused equipment being stored on location.

Inspection Photos  
Location Name: Razor 33M Pad  
Location ID: 431440



**Photo 2.** Close-up photo of pump jack motor, indicating fresh oil and oil staining on foundation of motor skid.




Inspection Photos  
Location Name: Razor 33M Pad  
Location ID: 431440



**Photo 3.** Facing south near the wellheads. Photo illustrates that the disturbance areas appear to have been reclaimed with evidence of vegetation establishment. It should be noted that some undesirable vegetation (e.g. kochia and russian thistle) was observed throughout the reclaimed/interim areas and accumulations of tumbleweeds around fence lines and equipment.

Inspection Photos  
Location Name: Razor 33M Pad  
Location ID: 431440



**Photos 4 & 5.** Facing west and south; see comments in Photo 3.