

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334906

Location Name: BENZEL-67S93W/2NESE

Inspection Document #: 702801212

Garfield County, CO

NESE Section 2 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-67S93W/2NESE
Location ID: 334906



Photo 1. Photo taken from the south shows an overview of the location.

Inspection Photos
Location Name: BENZEL-67S93W/2NESE
Location ID: 334906



Photo 2. Photos show two (2) risers which appear to be associated with a plugged and abandoned well and decommissioned flowline.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801212

Inspection Photos
Location Name: BENZEL-67S93W/2NESE
Location ID: 334906



Photo 3. Photos show production areas.

Inspection Photos
Location Name: BENZEL-67S93W/2NESE
Location ID: 334906



Photo 4. Photo shows an example of interim areas. Perennial grasses appear established.

