

# Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334851

Location Name: BENZEL-67S93W/1NWSW

Inspection Document #: 702801218

Garfield County, CO

NWSW Section 1 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**


Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-67S93W/1NWSW  
Location ID: 334851



**Photo 1.** Photo taken from the south shows an overview of the location.

Inspection Photos  
Location Name: BENZEL-67S93W/1NWSW  
Location ID: 334851



**Photo 2.** Photo shows a bull plug not installed on a tank drain line.

Inspection Photos  
Location Name: BENZEL-67S93W/1NWSW  
Location ID: 334851



2/1/23  
+39.472157,-107.731680  
39° NE



**Photo 3.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801218



Inspection Photos  
Location Name: BENZEL-67S93W/1NWSW  
Location ID: 334851



**Photo 4.** Photo shows an example of interim areas. Perennial grasses appear established.