

Construction and Stormwater Inspection

February 6, 2023

Operator: Extraction Oil and Gas, #10459

Location ID: 449925

Inspection Document #: 709400008

Adams, CO

SWSE, Section 25, 1S66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Alma/1S-66-2524 PAD

Location ID: 449925




Photo 1. Photo taken at the entrance of the location facing south toward the county road.

Photo 2. Photo taken at the entrance of the location facing north toward the location of the tracking device.



Inspection Photos

Location Name: Alma/1S-66-2524 PAD

Location ID: 449925




Photo 3. Photo taken at the southwest corner of the site. Operator shall comply with Rule 1002.e.(1)

Photo 4. see photo 3 comment



Inspection Photos

Location Name: Alma/1S-66-2524 PAD

Location ID: 449925



Photo 5. Photo taken on location next to well Alma west 26W-20-03. Large hole outside of fenced area no protective barrier to humans or wildlife present.

Photo 6. see photo 5 comment

