

# Stormwater Inspection

February 7th, 2023

Operator: Verdad Resources LLC, #10651

Location ID: 439158

Inspection Document #: 709400011

Weld, CO

SESW, Section 30, 1N65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Johnson  
Location ID: 439158



**Photo 1.** Photo of location sign at entrance of the pad.



**Photo 2.** Facing south toward county road 4 from location entrance. Evidence of tracking on to the pavement.

Inspection Photos  
Location Name: Johnson  
Location ID: 439158



**Photo 3.** See photo 2 comments

Inspection Photos  
Location Name: Johnson  
Location ID: 439158



**Photo 4.** Entrance of location looking north of vehicle tracking device BMP is in non-proper functioning condition.

**Photo 5.** See photo 4 comments