

# Interim Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320603

Inspection Document #: 696105724

Adams County, CO

SWSW Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Leech 14-26  
Location ID: 320603



**Photo 1.** Facing west at the well location. Appears the operator has performed the corrective actions by having managed the undesirable vegetation identified by previous inspection.

Inspection Photos  
Location Name: Leech 14-26  
Location ID: 320603



**Photo 2.** Facing southwest at the well location, see comments in Photo 1.

Inspection Photos  
Location Name: Leech 14-26  
Location ID: 320603



**Photo 3.** Facing east along the access road, see comments in Photo 1.