

# Inspection Photos

February 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324102

Location Name: CLOUGH-66S94W/20SWSW

Inspection Document #: 702801246

Garfield County, CO

SWSW Section 20 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



2/7/23  
+39.504393,-107.919741  
70° E

**Photo 1.** Photos taken from the west shows an overview of production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801246

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



Photo 2. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801246

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



**Photo 3.** Photos show stormwater BMPs to the south of the access road. Stormwater discharged from the BMPs is causing scouring resulting in gully erosion (right).

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



Photo 4. Photos show runoff from the access road causing erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources


Inspection Number: 702801246

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



**Photo 5.** Photos show rill erosion occurring throughout BMPs to the southeast of the location, particularly on sediment trap walls. Trap erosion is acting as an additional sediment source.

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



**Photo 6.** Photos show rill erosion occurring throughout BMPs to the southeast of the location, particularly on sediment trap walls. Trap erosion is acting as an additional sediment source.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801246

Inspection Photos

Location Name: CLOUGH-66S94W/20SWSW

Location ID: 324102



Photo 7. Photos show rill erosion, scouring and undercutting of rock armor occurring throughout BMPs to the southeast of the location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801246

Inspection Photos  
Location Name: CLOUGH-66S94W/20SWSW  
Location ID: 324102



**Photo 8.** Photos shows additional BMPs which are snow covered. Follow up inspection required to assess snow covered areas. Note erosion degradation in sediment trap to the northwest (right).



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801246