

# Interim Reclamation and Stormwater Inspection

Date: 02/10/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 455519

Inspection Document #: 696105734

Weld County, CO

E2SE Section 14 T8N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 1 & 2.** Facing west and northeast from top of topsoil stockpile. Photos illustrate that areas of bare soil and undesirable vegetation (e.g. russian thistle and kochia) were observed during this inspection.

## Inspection Photos

Location Name: Boomslang Fed 8-60 14B

Location ID: 455519



**Photos 3 & 4.** Close-up photos taken from topsoil stockpile on southern portion of the location. See comments in Photos 1 & 2.

## Inspection Photos



Location Name: Boomslang Fed 8-60 14B

Location ID: 455519



**Photos 5 & 6.** Facing northwest from the northern portion of the location. Photos taken from the interim area illustrating some undesirable vegetation (e.g. russian thistle and kochia) observed; the operator will have to manage for weedy vegetation during the 2023 growing season.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 7 & 8.** Facing west and east near the wellheads. Photos illustrates tumbleweed accumulations around equipment. This is considered debris and needs to be removed as it presents a fire hazard.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 9 & 10.** Facing northeast and northwest from the southeastern portion of the location. See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 11 & 12.** See comments in Photos 7 & 8.

# Inspection Photos


Location Name: Boomslang Fed 8-60 14B

Location ID: 455519



**Photos 13 & 14.** See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 15 & 16.** See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 17 & 18.** See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 19 & 20.** See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photos 21 & 22.** See comments in Photos 7 & 8.

Inspection Photos  
Location Name: Boomslang Fed 8-60 14B  
Location ID: 455519



**Photo 23.** Facing southeast near the production equipment. Photo illustrates the the wildlife netting is inadequate and needs to be repaired to exclude wildlife entry to the secondary containment area.