

Interim Reclamation and Stormwater Inspection

Date: 02/10/2023

Operator: MALLARD EXPLORATION LLC - 10670

Location ID: 455657

Inspection Document #: 696105738

Weld County, CO

NWNE Section 27 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 1. Facing northwest towards the wellheads. Tumbleweeds were observed throughout the with accumulations in and around equipment. This is now considered debris and needs to be removed as it's a fire hazard.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 4. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 5. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 6. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 7. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



2/10/23, 10:30 AM
79° E
COGCC

Photo 8. See comments in Photo 1.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 9. Facing south from the eastern side of the location. It appears interim reclamation activities have been performed with evidence of drill rows and mulch application. An inspection will be performed at a later date to ensure compliance with Rule 1003.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 10. Facing south from the western side of the location. See comment sin Photo 9.

Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657



Photo 11. Facing east from the southern portion of the location. See comments in Photo 9.