

Interim Reclamation and Stormwater Inspection

Date: 02/10/2023

Operator: SUMMIT OIL & GAS - 10774

Location ID: 465272

Inspection Document #: 696105740

Weld County, CO

SWSE Section 12 T7N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 1. Facing west at treater; Photo illustrates that the stained soil and equipment has been cleaned up. Operator stated on FIRR (Doc #403313860) that treater has been repaired.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 2. Facing east at the tank battery; it appears the operator has performed the previous corrective action and has cleanup up the free fluid on the tanks. Operator also stated on FIRR (Doc #403313860) that equipment has been repaired.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 3. See comments in Photo 2.



Photo 4. Facing west from the northeastern corner of the location, near the tank battery. Photo illustrates rill erosion on the eastern wall of the perimeter ditch/berm. This BMP will need to be repaired/maintained to prevent sediment from traveling off location.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 5. See comments in Photo 4.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 6. Facing southeast near the eastern side of the location. Trash was observed throughout the location and will need to be picked up. Also pictured, undesirable vegetation (e.g. russian thistle and kochia) was observed throughout and will need to be managed during the next growing season. A follow-up inspection will be performed at a later date to ensure compliance with Rule 1003, including weed management.



Photo 7. Trash observed within the tank battery secondary containment area.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 8. Close-up photo of trash observed on the west side of the tank battery.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 9. Facing east from the top of the topsoil stockpile. The topsoil stockpile is void of vegetation resulting in large areas of bare soil.

Inspection Photos
Location Name: Castor 7-59 12
Location ID: 465272



Photo 10. Facing west, see comments in Photo 9.