

TEP Rocky Mountain LLC GM 14-27 Pad Location #335306



Entrance to location



Tank battery sign

TEP Rocky Mountain LLC
GM 14-27 Pad
Location #335306



Pad separators

Debris

**TEP Rocky Mountain LLC
GM 14-27 Pad
Location #335306**



Unmarked deadman. NW corner

Sediment trap erosion

**TEP Rocky Mountain LLC
GM 14-27 Pad
Location #335306**



Lack of maintenance

Erosion underneath wattle

TEP Rocky Mountain LLC
GM 14-27 Pad
Location #335306



Plugged drainage ditch

Plugged ditch diverting runoff over lease road