

**TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318**



Entrance to well pad.



Well pad to production facility.

TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318



Entrance to production facility.



Illegible tank battery sign.

**TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318**




Unidentified tank capacity.




Open end loadline.

TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318



Unused equipment.



Unused equipment. Out of service.

**TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318**



Debris at separators.



Sediment encroachment.

**TEP Rocky Mountain LLC
GM 323-28 Pad
Location #335318**



Limited Stormwater BMP.



Exit from Production pad.