

Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 323153

Inspection Document #: 708000019

Weld County, CO

SENW Section 1 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AMIGO 2
Location ID: 323153



Photo 1. Google Earth aerial imagery taken 6/2016 during active operations. Photo illustrates the well location (red circle), tank battery (red square), flowline (red line), and well location access road (white arrow).

Inspection Photos
Location Name: AMIGO 2
Location ID: 323153



Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near 1) and flowlines (black lines). Flowline abandonment/removal not submitted.

Inspection Photos
Location Name: AMIGO 2
Location ID: 323153





Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept 2022). Photo illustrates growth on and around the well location (red circle), flowline, tank battery (red rectangle) and access road. Re-vegetation has not fully occurred on well site, access road or tank battery. Red line is approximate flowline; Blue line is approximate flowline and access road.

Inspection Photos
Location Name: AMIGO 2
Location ID: 323153



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept 2022). Illustrates lack of full growth on and around the well location (red circle) and access road (blue line).

Inspection Photos
Location Name: AMIGO 2
Location ID: 323153



N →

Photo 5. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept 2022). Illustrates lack of growth on and around the tank battery (red rectangle) and access road (blue line).