

# Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 317717

Inspection Document #: 708000079

Weld County, CO

NESW Section 6 4N63W 6

Kasen Huwa

Reclamation Contractor, COGCC



**COLORADO**


**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Google Earth aerial imagery taken 6/2016 during active operations. Photo illustrates the well locations (red circle) and tank battery (red rectangle).

Inspection Photos  
Location Name: SPIKE STATE #CC 6-11J  
Location ID: 317717



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (left center of picture), and flowlines (black lines). Flowline abandonment is not submitted.



Inspection Photos  
Location Name: SPIKE STATE #CC 6-11J  
Location ID: 317717



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle) and approximate flowlines (red lines). Tank battery addressed in Location 328608 report.



Inspection Photos  
Location Name: SPIKE STATE #CC 6-11J  
Location ID: 317717



**Photo 4.** Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.