

# Final Reclamation Inspection

October 07, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 329672

Inspection Document #: 708000213

Weld County, CO

NWNW Section 33 3N65W 6

Kasen Huwa  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: UPRC \*33-4J5  
Location ID: 329672




**Photo 1.** Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowline (red line).

Inspection Photos  
Location Name: UPRC \*33-4J5  
Location ID: 329672



**Photo 2.** COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near northwest corner) and flowlines (black lines).



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates rangeland growth on and around the well location (red circle), flowline (red line), and tank battery (red rectangle).

Inspection Photos  
Location Name: UPRC \*33-4J5  
Location ID: 329672



**Photo 4.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates rangeland growth similar to surroundings on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.



**Photo 5.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates rangeland growth on and around the tank battery (red rectangle) however bare dirt are still visible.