

KPK  
South McCallum tank battery  
Location # 480891



location



location pump jack and well head



KPK  
South McCallum tank battery  
Location # 480891



**Tank battery lacking signage**



**Diesel tank lacking secondary containment**





KPK  
South McCallum tank battery  
Location # 480891



**Previous inspection of staining and leaking stuffing box**



KPK  
South McCallum tank battery  
Location # 480891



**Follow up inspection of staining and leaking stuffing box**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



KPK  
South McCallum tank battery  
Location # 480891



**Previous inspection of thief hatch open**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

KPK  
South McCallum tank battery  
Location # 480891



**Follow up inspection of thief hatch closed**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

KPK  
South McCallum tank battery  
Location # 480891



Feb 15, 2023 at 9:33:44 AM  
+40.715450,-106.134355 ±18.16m  
CCCCC

**Previous inspection photo of debris and propane torch next to tanks.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



KPK  
South McCallum tank battery  
Location # 480891



**Follow up photo of debris still present. Propane torch removed**



KPK  
South McCallum tank battery  
Location # 480891



**Open for wild life to enter and debris from previous inspection**



KPK  
South McCallum tank battery  
Location # 480891



Feb 15, 2023 at 9:34:54 AM  
+40.715372,-106.134455 ±4.60m

**Random debris, open line and staining photo from previous inspection**



KPK  
South McCallum tank battery  
Location # 480891



Debris and staining are still present. Line on tank missing cap and evidence of burn marks around pipe. Insulation is melted and tin is charred.



Evidence of burn marks around pipe. Insulation is melted and tin is charred.



**KPK**  
**South McCallum tank battery**  
**Location # 480891**



**Line on tank missing cap and evidence of burn marks around pipe. Insulation is melted and tin is charred.**



**Line on tank missing cap and evidence of burn marks around pipe. Insulation is melted and tin is charred.**





**KPK**  
**South McCallum tank battery**  
**Location # 480891**



**Random debris still in place**



**Signage is not legible from distance**

