

Operator: CIVITAS NORTH LLC

Location Name: State 16-7-60 1H

Loc ID: 432352

Inspection: 696105746



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G

CA: Tumbleweeds were observed throughout the location, with accumulations in and around equipment. Debris will need to be removed from location to comply with Rule 606.

CA Resolution: Weeds were removed from the equipment on 2/17/2023 to comply with Rule 606. Housekeeping tasks to manage the weeds throughout the location will continue. Once ground conditions improve, bare areas will be re-seeded and weeds will be sprayed/mowed as needed.