

# Inspection Photos

February 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334622

Location Name: ROSE RANCH-67S93W/14NWNW

Inspection Document #: 702801269

Garfield County, CO

NWNW Section 14 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: ROSE RANCH-67S93W/14NWNW**  
**Location ID: 334622**



**Photo 1.** Photos taken from the entrance show an overview of the location to the west (left) and east (right).



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Number: 702801269

Inspection Photos  
Location Name: ROSE RANCH-67S93W/14NWNW  
Location ID: 334622



**Photo 2.** Photos show production areas. A tank battery sign is absent (left).



Inspection Photos  
Location Name: ROSE RANCH-67S93W/14NWNW  
Location ID: 334622



**Photo 3.** Photos show production areas.





Inspection Photos

Location Name: ROSE RANCH-67S93W/14NWNW

Location ID: 334622



**Photo 4.** Photo shows an example of interim areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801269