

# Inspection Photos

February 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334617

Location Name: PARKER RANCH-67S93W/15SENE

Inspection Document #: 702801272

Garfield County, CO

SENE Section 15 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: PARKER RANCH-67S93W/15SENE  
Location ID: 334617



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: PARKER RANCH-67S93W/15SENE  
Location ID: 334617



Photo 2. Photos show production areas. A tank battery sign is absent (left).



Inspection Photos

Location Name: PARKER RANCH-67S93W/15SENE

Location ID: 334617



**Photo 3.** Photo shows an example of interim areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801272