

Inspection Photos

February 13, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334940

Location Name: HMU-67S93W/3NESE

Inspection Document #: 702801278

Garfield County, CO

NESE Section 3 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HMU-67S93W/3NESE
Location ID: 334940



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: HMU-67S93W/3NESE
Location ID: 334940



Photo 2. Photos show production areas. Tank battery sign is absent.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801278

Inspection Photos
Location Name: HMU-67S93W/3NESE
Location ID: 334940



Photo 3. Photos show production areas.

Inspection Photos

Location Name: HMU-67S93W/3NESE

Location ID: 334940



Photo 4. Photo shows an example of interim areas. Introduced perennial grasses and native shrubs appear established.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801278