

# Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 329751

Inspection Document #: 708000299

Weld County, CO

NWSE Section 3 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: OSTER #3-1014  
Location ID: 329751




**Photo 1.** Google Earth aerial imagery taken 6/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Inspection Photos  
Location Name: OSTER #3-1014  
Location ID: 329751



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (south center) and flowlines (black lines).

Inspection Photos  
Location Name: OSTER #3-1014  
Location ID: 329751



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle) and flowlines (red lines). Tank Battery is addressed in Location 310883 report.





**Photo 4.** Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates lack of growth on and around the well location (red circle).