

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Kunsemiller 5-61-20_19 NW21

Loc ID: 434508

Inspection: 696304665



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Tumbleweeds were observed at Gas Meters and Separators. Debris will need to be removed from location to comply with Rule 606.

CA Resolution: Weeds were removed from the equipment on 2/20/2023 to comply with Rule 606. Operator will continue to manage the weeds throughout the location.