



Inspection Photos

Location Name: Bashor 9-60 27B Pad

Location ID: 455657



Photo 1. Facing northwest towards the wellheads. Tumbleweeds were removed throughout the site equipment. This is now removed.



Inspection Photos

Location Name: Bashor 9-60 27B Pad

Location ID: 455657






Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657





Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657





Inspection Photos

Location Name: Bashor 9-60 27B Pad

Location ID: 455657





Inspection Photos
Location Name: Bashor 9-60 27B Pad
Location ID: 455657

