

Operator: EXTRACTION OIL & GAS INC

Location Name: Varra/5-I Pad

Loc ID: 430411

Inspection: 679605453



Exhibit A

CA: Observed stained soil at the wellhead. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.(2).D.

CA Resolution: The operator was able to clean up the stained rock to comply with Rule 1002.(2).D.