

# Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 3/1/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 2.** There is oil stained soil around the tank from a spill contained inside the bermed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 3.** There is a puddle of oil which appears to be a shallow hole where oil has accumulated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 4.** There is oil staining around the tanks which needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 5.** The container at red arrow was position to catch oily waste at the whit pipes which has been displaced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 6.** South side of the location facing north at the location. There are unmarked pipe risers at this side of the location which should be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 7.** There is a propane bottle which is not in use and needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 8.** Facing northeast toward the storage shed. There is various unused parts and equipment that needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 9.** There are unlabeled containers with unknown substance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 10.** There is various unused unnecessary equipment/supplies being stored at the location. All supplies not necessary for use on the location is prohibited.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 150396 | Date: 3/1/2023

## Inspection Photos



**Photo 11.** There is various unused unnecessary equipment/supplies being stored at the location. All unused equipment not necessary for use on the location is prohibited and must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023



## Inspection Photos



**Photo 12.** There is an electric wire on the ground which can be a safety issue as it is not properly protected. Sign is posted at the battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150396 | Date: 3/1/2023