

Operator: CRESTONE PEAK RESOURCES

Location Name: Grande 4-65 20-19 3AH

Loc ID: 450063

Inspection: 706700306



Exhibit A

CA: 40 bbl water tank for frac is not labeled. Determine if netting is needed on the open top tank. Install sign to comply with Rule 605.h on next frac location/Sky Ranch South.

CA Resolution: Signage/labels have been installed to comply with Rule 605.h on next frac location/Sky Ranch South.