

# Environmental Inspection

March 1, 2023

Operator: D09 ENERGY LLC - #10706

Location ID: 436007

Spill ID: 483729

Inspection Document #: 690900233

Jackson County, CO

NENW Section 32 T8N R80W

Alex Fischer

Environmental Supervisor - Western Colorado, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Grizzly 3-32H  
Location ID: 436007



Photo 1. Sign at tank battery.

Inspection Photos  
Location Name: Grizzly 3-32H  
Location ID: 436007



**Photo 2.** Valve leaking on middle easternmost Produced Oil tank.



**Photo 3.** Tank with leaking valve.



Inspection Photos  
Location Name: Grizzly 3-32H  
Location ID: 436007



**Photo 4.** Liner with holes and repair. Note: Arrow points to Duct Tape repair. Circle depicts pen through liner penetration.



**Photo 5.** Liner with holes and repair. Note: Arrow points to Duct Tape repair. Circle depicts pen through liner penetration

Inspection Photos  
Location Name: Grizzly 3-32H  
Location ID: 436007



**Photo 4.** Liner with holes and repair. Note: Arrow points to Duct Tape repair. Circle depicts pen through liner penetration.



**Photo 5.** Liner with holes and repair. Note: Arrow points to Duct Tape repair. Circle depicts pen through liner penetration