

# LARAMIE ENERGY LLC, Shell/797-09A

Location # 335018



Location – Photo #01111



Wellhead/Chemical Tank – Photo #01115



# LARAMIE ENERGY LLC, Shell/797-09A

Location # 335018



Casing Flange Leak (Bubbling) – Photo #01117



Separators – Photo #01131



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



# LARAMIE ENERGY LLC, Shell/797-09A

Location # 335018



**Tank Battery – Photo #01120**



**Open-Ended Load Line – Photo #01126**



# LARAMIE ENERGY LLC, Shell/797-09A

Location # 335018



Unused Equipment – Photo #01124



Pigging Station – Photo #01114

