

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 41-3 pad

Location ID: 323965



Photo # 1800 From entrance to location



Photo # 1801 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 41-3 pad

Location ID: 323965



Photo # 1802 From entrance to location



Photo # 1803 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 41-3 pad

Location ID: 323965



Photo # 1804 Location



Photo # 1805 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 41-3 pad

Location ID: 323965



Photo # 1807 Open ended load line



Photo # 1808 Open ended pipe on production tank

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 41-3 pad

Location ID: 323965



Photo # 1809 Unmarked deadman



Photo # 1829 Unmarked deadman