

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #414231

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #414231



Photo 1: Conductor plugging/reclamation “in process”.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #414231



March 6, 2023

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #414231



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #414231



Photo 4: Signage at tank battery.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #414231



March 6, 2023

Photo 5: BMPs along access road showing signs of disrepair. Maintenance advised prior to failure of BMP.