

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #324199

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 1: Photo example showing liner integrity at the tank battery remains compromised.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199




Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 5: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 6: Photos show stockpiled soils along the east end of the Location; soils unconsolidated and are a pollutant source; BMPs to minimize sediment transport missing or insufficient; soils observed covering vegetation.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 7: See comments under photo 6. Photo shows soils stockpiled on east end of the Location are covering vegetation; BMPs to minimize sediment transport missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 6: Photo example showing BMPs to minimize tracking and degradation are missing or insufficient on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



March 6, 2023



March 6, 2023

Photo 9: Photo left taken from the access road at the Location entrance. Photos examples showing BMPs to manage runoff, minimize tracking, degradation and sediment transport are missing or insufficient along the main North/South access road leading to the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 10: Photos example showing tracking, degradation and sediment transport along access road; BMPs to manage runoff, minimize tracking, degradation and sediment transport are missing or insufficient along the main North/South access road leading to the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #324199



Photo 11: Photos example showing tracking, degradation and sediment transport along access road; BMPs to manage runoff, minimize tracking, degradation and sediment transport are missing or insufficient along the main North/South access road leading to the Location.