

# Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335795

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795




**Photo 1:** Photos 1-4 examples showing liner integrity at the tank battery remains compromised.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795



**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795



**Photo 3:** See comments under photo 1.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335795



**Photo 4:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795



**Photo 5:** Photos 5-7 examples showing tracking, degradation and sediment transport along access road; BMPs to manage runoff, minimize tracking, degradation and sediment transport are missing or insufficient along the main North/South access road leading to the Location.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795



**Photo 6:** See comments under photo 5.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335795



**Photo 7:** See comments under photo 5.