

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335581

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335581



Photo 1: Tank battery



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335581



Photo 2: Cracks observed in liner.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335581



Photo 3: Photos example showing BMPs to degradation, tracking and sediment transport are missing or insufficient on the Location.