

# Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335596


Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 1:** Location overview; BMPs to stabilize the working pad, as well as to minimize degradation, tracking and sediment transport do not appear to be adequate during wet conditions.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 2:** Sign/Label at tank no longer legible.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335596



**Photo 3:** Unused pipe equipment stored within containment berm.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 4:** Photo shows various tears/holes observed within liner; liner no longer impervious to contain a spill.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 5:** Photo taken from the location entrance. Photo shows BMPs to minimize degradation, tracking and sediment transport are missing or insufficient at the Location and access road.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 6:** Photos 6-11 examples showing BMPs to manage runoff, minimize degradation, tracking and sediment transport are missing or insufficient at the access road.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 7:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 8:** See comments under photo 6.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



March 6, 2023

**Photo 9:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 10:** See comments under photo 6.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location #335596



**Photo 11:** See comments under photo 6.