

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335793

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location #335793



Photo 1: Photos shows secondary containment BMPs at the tank battery has filled with fluids/ice, and does not appear adequate to contain a spill.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 2: Photo shows secondary containment BMPs at the tank battery has filled with fluids/ice, and does not appear adequate to contain a spill.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 3: Photos 3-8 examples showing BMPs to manage runoff, minimize degradation, tracking and sediment transport are missing or insufficient at the access road.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 5: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



March 6, 2023

Photo 6: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 7: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335793



Photo 8: See comments under photo 3.