

Inspection Photos

3/06/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #335780

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 1: Photos left shows signage missing from the 24B-12D well. Photo right example showing remaining signs are becoming illegible.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 2: Photos 2-3 examples showing various holes/tears observed throughout liner at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 3: See comment under photo 2.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 4: Photos 4-8 examples showing BMPs to stabilize, as well as to minimize degradation, tracking and sediment transport are missing or insufficient at the Location and access road.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 6: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 7: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #335780



Photo 8: See comments under photo 4.