

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 266-3 Pad

Location ID: 334596



**Photo # 1811 From entrance to location.**



**Photo # 1812 From entrance to location.**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 266-3 Pad

Location ID: 334596



Photo # 1813 Location



Photo # 1814 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 266-3 Pad

Location ID: 334596



Photo # 1815 Location





Photo # 1817 Wellhead sign missing

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 266-3 Pad

Location ID: 334596



**Photo # 1822 Stormwater – Materials Handling & Spill  
Prevention improper storage**



**Photo # 1824 Open ended load line**