

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 267-3 Pad

Location ID: 324120



Mar 7, 2023 at 12:40:46 PM  
CO



Mar 7, 2023 at 12:40:49 PM  
CO

Photo # 1832 From entrance to location

Photo # 1833 From entrance to location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 267-3 Pad

Location ID: 324120



Photo # 1835 Location



Photo # 1836 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 267-3 Pad

Location ID: 324120



Photo # 1838 Location



Photo # 1839 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 267-3 Pad

Location ID: 324120



Photo # 1837 Battery sign missing

