

CAERUS PICEANCE LLC, COWPERTHWAIT-68S97W/6SWNW

Location # 322458



Location – Photo #01308



Wellhead/Chemical Tank – Photo #01309



CAERUS PICEANCE LLC, COWPERTHWAIT-68S97W/6SWNW

Location # 322458



Separator – Photo #01312




Tank Battery – Photo #01310



CAERUS PICEANCE LLC, COWPERTHWAIT-68S97W/6SWNW

Location # 322458



Pig Station – Photo #01315



Summit Midstream Meter – Photo #01316



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

CAERUS PICEANCE LLC, COWPERTHWAIT-68S97W/6SWNW

Location # 322458



Lack of Stabilization – Photo #01313



Lack of Stabilization – Photo #01317