

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2089 From entrance to location



Photo # 2090 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2091 From entrance to location



Photo # 2094 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2098 Location



Photo # 2110 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2099 Location



Photo # 2095 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2144 Location – Chemical tanks & chemical BMP's



Photo # 2145 Chemical BMP not maintained

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2146 Chemical BMP not maintained



Photo # 2147 Chemical BMP not maintained

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2148 Chemical BMP not maintained



Photo # 2106 Calibration info not conspicuously posted

Inspection Photos

Location Name: CAERUS PICEANCE LLC NPR 004-696 Pad

Location # 414231



Photo # 2107 Calibration info not conspicuously posted