

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Mar 9, 2023 at 2:28:06 PM



Mar 9, 2023 at 2:28:08 PM

Photo # 2111 From entrance to location

Photo # 2112 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2113 From entrance to location



Photo # 2114 From entrance to Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2115 From Entrance to location



Photo # 2116 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2117 Location



Photo # 2118 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2119 Location



Photo # 2120 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2157 Chemical tanks & BMP's



Photo # 2153 Chemical BMP not maintained



Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2155 Chemical BMP not maintained



Photo # 2156 Chemical BMP not maintained

Inspection Photos

Location Name: CAERUS PICEANCE LLC MF09A N04 696 Pad

Location # 335598



Photo # 2123 Calibration info not conspicuously posted



Photo # 2125 Calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources