

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /36SENE

Location ID: 334926



Photo #9152 From entrance to location.



Photo #9153 From entrance to location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /36SENE

Location ID: 334926



Photo #9154 From entrance to location.




Photo #9158 Meter calibration card not conspicuously posted.