

Interim Reclamation and Stormwater Inspection

Date: 03/08/2023

Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 310566

Inspection Document #: 708200043

Weld County, CO

NENE Section 1 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photos 1 & 2. Facing south and northwest at well.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 3. Facing north along access road. Rill erosion was occurring along the access road to the well. The affected area will need to be stabilized to prevent further sediment transport and degradation to adjacent lands.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 4. Facing northeast; see comments in Photo 3.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 5. Facing southeast; See comments in Photo 3.

Inspection Photos
Location Name: Green 1-1
Location ID: 310566



Photo 6. Facing southwest. Additional rill erosion occurring south of previous photos.