

Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Location



Location and lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
Savage Federal 1-43
Location # 324029




Location



location



Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Location



Stored equipment



Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Stored equipment



Stored equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Access road lack of stabilization with sediment migration



Access road lack of stabilization with sediment migration



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Access road lack of stabilization with sediment migration



Location shows signs of lack of stabilization/compaction

**Caerus Piceance LLC
Savage Federal 1-43
Location # 324029**



Location shows signs of lack of stabilization/compaction



Access road lack of stabilization with sediment migration



Caerus Piceance LLC
Savage Federal 1-43
Location # 324029



Access road lack of stabilization with sediment migration



Location shows signs of lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Caerus Piceance LLC
Savage Federal 1-43
Location # 324029**



Location entrance with tracking from location

