

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 239-29 Pad

Location ID: 324112



Photo # 2162 From entrance to location



Photo # 2163 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 239-29 Pad

Location ID: 324112



Photo from Inspection 700704654 taken 10/27/2022, API # missing



Photo # 2320 API # added, but is incorrect

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 239-29 Pad

Location ID: 324112



**Access entrance CA photo from Inspection # 700704654
conducted on 10/27/2022**



Photo # 2322 Entrance to access road